		INSPE	CTION INF	ORMATION				
MAKER	KARCHER		BLADE			Have	☐ No	
SPECIES	SWEEPER		TIRE SIZE		145/80F	R1069T	☐ Tube ☐	Tubeless
MODEL, SERIAL NO. ICC1-W0914201144K88198				Maker		KUBOTA		
PLATE NO. ICC1-W0914		201144K88198	ENGINE		Model	D722		
STAMP				S/No.	4N0577			
YEAR MANUFACTURE	UFACTURE 2012 Yr.		EPA		✓	Have	☐ No	
SERVICE METER	63 Hrs.		FRONT		☐ Std	Offset	Super Long	М
SERVICE WETER	Confirmed	Unreliable	PRONT		☐ 2Sec	☐ 3Sec	Demotion	М
SHOE WIDTH / TYPE			CAB		Rops	✓ Cab	☐ Canopy	☐ None
PIPING		☐ No	CAB		☐ With Air	cond	✓ Without Ai	r Cond
ATTACHMENT			排ガス規制					
BUCKET			書類	有				
CHECK VALVE(クレーン付き)	☐ Have	□ No	MULTI LEVER			Have	☐ No	
	esel Engine, 101KM							
NOTE クボタディーも	ヹルエンジン、101KM							
☐ Straight Dozer	Without Tilt	☐ Angle	Dozer	☐ 6way	Dozer			
☐ Direct Drive ☐ Power Shift ☐ Differential		Steering Power Shift Direct Powershift H.S.T.						
☐ With Multi Ripper	☐ 2 Cylinder	☐ 4 Cylin	nder	Shank				
☐ With Giant Ripper	2 Cylinder	☐ 4 Cylin						
☐ 2Lever ☐4Lever	☐ Wrist Contro	ol 🗆	Finger Stick	☐ With	Ride Control	☐ Witho	ut Ride Control	
ENGINE	✓ Good	☐ Fair	☐ Bad	☐ Oil Leaking				
MAIN PUMP	✓ Good	☐ Fair	☐ Bad	Oil Leaking				
SWING BEARING	Good	☐ Fair	☐ Bad	☐ Oil Leaking	N/A			
TRAVEL MOTOR	Good	☐ Fair	☐ Bad	Oil Leaking	N/A			
TRANSMISSION	Good	☐ Fair	☐ Bad	Oil Leaking	N/A			
TORQUE CONVERTOR	Good	☐ Fair	☐ Bad	_	N/A			
BRAKING SYSTEM	✓ Good	☐ Fair	☐ Bad	_				
APPEARANCE	✓ Good	☐ Fair	☐ Bad	_				
UNDER CARRIAGE / TIRI	✓ Good	☐ Fair	☐ Bad	_				
BOOM / CYLINDER	☐ No Crack	Welded	☐ Patched	☐ Oil Leaking	N/A			
ARM / CYLINDER	☐ No Crack		☐ Patched	☐ Oil Leaking	N/A			
BATTERY	✓ Good	☐ Need To Ch	narge 🗆	Need To Change				
COMMENT								

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。