INSPECTION INFORMATION							
MAKER	HITACHI		BLADE			Have	✓ No
SPECIES	EXCAVATOR		TIRE SIZE				☐ Tube ☐ Tubeless
MODEL, SERIAL NO.	ZX225USRK-3-218146				Maker		ISUZU
PLATE NO.		ENGINE		Model		4HK1	
STAMP					S/No.	472338	
YEAR MANUFACTURE	2011	Yr.	EPA		V	Have	□ No
CEDVICE METER	8056	Hrs.	FRONT		☑ Std	☐ Offset	Super M
SERVICE METER	✓ Confirmed	Unreliable			☐ 2Sec	☐ 3Sec	☐ Demotion M
SHOE WIDTH / TYPE 6000		00G			Rops	✓ Cab	☐ Canopy ☐ None
PIPING	✓ Have(5pipes)	☐ No	CAB		✓ With Air	cond	☐ Without Air Cond
ATTACHMENT	,		排ガス規制		3次排ガス		
BUCKET			書類	有 無			
CHECK VALVE(クレーン付き)	✓ Have	☐ No	MULTI LEVER			Have	☐ No
NOTE							
☐ Straight Dozer	☐ With Tilt		Without Tilt	☐ Angle	Dozer	☐ 6way I	Dozer
☐ Direct Drive ☐ Power Shift ☐ Differential Steering Power Shift ☐ Direct Powershift ☐ H.S.T.							
☐ With Multi Ripper	☐ 2 Cylinder	☐ 4 Cylin	ider 🗌	Shank			
☐ With Giant Ripper ☐ 2 Cylinder ☐ 4 Cylinder							
☐ 2Lever ☐4Lever	☐ Wrist Contro	ol 🗆	Finger Stick	☐ With I	Ride Control	☐ Withou	ut Ride Control
ENGINE	☐ Good	✓ Fair	Bad	☐ Oil Leaking			
MAIN PUMP	Good	✓ Fair	☐ Bad	☐ Oil Leaking			
SWING BEARING	Good	✓ Fair	Bad	☐ Oil Leaking			
TRAVEL MOTOR	Good	✓ Fair	☐ Bad	☐ Oil Leaking			
TRANSMISSION	Good	Fair	☐ Bad	☐ Oil Leaking	N/A		
TORQUE CONVERTOR	Good	☐ Fair	☐ Bad	_	N/A		
BRAKING SYSTEM	Good	☐ Fair	☐ Bad	_	N/A		
APPEARANCE	Good	✓ Fair	☐ Bad	_			
UNDER CARRIAGE / TIRE	Good	✓ Fair	☐ Bad	_			
BOOM / CYLINDER	✓ No Crack	Welded	☐ Patched	☐ Oil Leaking			
ARM / CYLINDER	✓ No Crack	Welded	☐ Patched	☐ Oil Leaking			
BATTERY	✓ Good	☐ Need To Ch	narge	Need To Change			
COMMENT			•				

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。