| | | INSPE | CTION INFO | ORMATION | | | | |
|---|-------------------|--------------|--------------|----------------|--------------|------------|-----------------|----------|
| MAKER | CAT | | BLADE | | | Have | ☐ No | |
| SPECIES | EXCA | VATOR | TIRE SIZE | | | | ☐ Tube ☐ T | Tubeless |
| MODEL, SERIAL NO. | 320E-2-SXE-03271 | | | | Maker | | CAT | |
| PLATE NO. CAT0320EHS) | | HSXE03271 | ENGINE | | Model | C6.6 | | |
| STAMP | CAT0320EHSXE03271 | | | | S/No. | C8N36766 | | |
| YEAR MANUFACTURE | 2016 | Yr. | EPA | | | Have | ✓ No | |
| SERVICE METER | 9495 | Hrs. | FRONT | | ✓ Std | ☐ Offset | Super Long | М |
| SERVICE METER | ✓ Confirmed | Unreliable | | | ☐ 2Sec | ☐ 3Sec | Demotion | М |
| SHOE WIDTH / TYPE 600G | | CAB | | ✓ Rops | ✓ Cab | ☐ Canopy [| None | |
| PIPING | ☐ Have | ✓ No | CAB | | With Air | cond | ☐ Without Air C | Cond |
| ATTACHMENT | | | 排ガス規制 | | 3.5次排ガス | | | |
| BUCKET | 0.8 M3 | | 書類 ☑ 有 □ 無 | | 譲渡証 | | | |
| CHECK VALVE(クレーン付き) | ☐ Have | ✓ No | MULTI LEVER | | ✓ | Have | ☐ No | |
| NOTE | | | | | | | | |
| ☐ Straight Dozer ☐ With Tilt ☐ Without Tilt ☐ Angle Dozer ☐ 6way Dozer | | | | | | | | |
| ☐ Direct Drive ☐ Power Shift ☐ Differential Steering Power Shift ☐ Direct Powershift ☐ H.S.T. | | | | | | | | |
| ☐ With Multi Ripper | 2 Cylinder | ☐ 4 Cylin | der | Shank | | | | |
| ☐ With Giant Ripper | 2 Cylinder | ☐ 4 Cylin | der | | | | | |
| ☐ 2Lever ☐4Lever | ☐ Wrist Contro | ol 🗆 | Finger Stick | ☐ With I | Ride Control | ☐ Withou | ut Ride Control | |
| ENGINE | Good | ✓ Fair | Bad | Oil Leaking | | | | |
| MAIN PUMP | Good | ✓ Fair | Bad | Oil Leaking | | | | |
| SWING BEARING | Good | ✓ Fair | ☐ Bad | Oil Leaking | | | | |
| TRAVEL MOTOR | Good | ✓ Fair | Bad | Oil Leaking | | | | |
| TRANSMISSION | Good | ☐ Fair | Bad | Oil Leaking | N/A | | | |
| TORQUE CONVERTOR | Good | ☐ Fair | Bad | 1 | N/A | | | |
| BRAKING SYSTEM | Good | Fair | Bad | 1 | N/A | | | |
| APPEARANCE | Good | ✓ Fair | Bad | _ | | | | |
| UNDER CARRIAGE / TIRE | Good | ✓ Fair | Bad | ı | | | | |
| BOOM / CYLINDER | ✓ No Crack | Welded | ☐ Patched | ☐ Oil Leaking | | | | |
| ARM / CYLINDER | ✓ No Crack | Welded | ☐ Patched | ☐ Oil Leaking | | | | |
| BATTERY | ✓ Good | ☐ Need To Ch | narge 🗆 | Need To Change | | | | |
| COMMENT | | | | | | | | |

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。