

INSPECTION INFORMATION

MAKER	KOMATSU	BLADE	<input checked="" type="checkbox"/> Have	<input type="checkbox"/> No			
SPECIES	BULLDOZER	TIRE SIZE	<input type="checkbox"/> Tube <input type="checkbox"/> Tubeless				
MODEL, SERIAL NO.	D85EX-15EO-11104	ENGINE	Maker	KOMATSU			
PLATE NO.	KMT0D101C01011104		Model	SAA6D125E-5			
STAMP	KMT0D101C01011104		S/No.	561271			
YEAR MANUFACTURE	2006 Yr.	EPA	<input checked="" type="checkbox"/> Have	<input type="checkbox"/> No			
SERVICE METER	14073 Hrs.	FRONT	<input type="checkbox"/> Std	<input type="checkbox"/> Offset	<input type="checkbox"/> Super Long	M	
	<input checked="" type="checkbox"/> Confirmed <input type="checkbox"/> Unreliable		<input type="checkbox"/> 2Sec	<input type="checkbox"/> 3Sec	<input type="checkbox"/> Demotion	M	
SHOE WIDTH / TYPE	GROUSER	CAB	<input checked="" type="checkbox"/> Rops	<input checked="" type="checkbox"/> Cab	<input type="checkbox"/> Canopy	<input type="checkbox"/> None	
PIPING	<input type="checkbox"/> Have <input type="checkbox"/> No		<input type="checkbox"/> With Air cond	<input type="checkbox"/> Without Air Cond			
ATTACHMENT		排ガス規制	2次排ガス				
BUCKET		書類	<input checked="" type="checkbox"/> 有	<input type="checkbox"/> 無			譲渡証
CHECK VALVE (クレーン付き)	<input type="checkbox"/> Have <input type="checkbox"/> No	MULTI LEVER	<input type="checkbox"/> Have		<input type="checkbox"/> No		
NOTE							

<input checked="" type="checkbox"/> Straight Dozer	<input checked="" type="checkbox"/> With Tilt	<input type="checkbox"/> Without Tilt	<input type="checkbox"/> Angle Dozer	<input type="checkbox"/> 6way Dozer	
<input type="checkbox"/> Direct Drive	<input checked="" type="checkbox"/> Power Shift	<input type="checkbox"/> Differential Steering Power Shift	<input type="checkbox"/> Direct Powershift	<input type="checkbox"/> H.S.T.	
<input checked="" type="checkbox"/> With Multi Ripper	<input checked="" type="checkbox"/> 2 Cylinder	<input type="checkbox"/> 4 Cylinder	<input checked="" type="checkbox"/> 3 Shank		
<input type="checkbox"/> With Giant Ripper	<input type="checkbox"/> 2 Cylinder	<input type="checkbox"/> 4 Cylinder			
<input type="checkbox"/> 2Lever	<input type="checkbox"/> 4Lever	<input type="checkbox"/> Wrist Control	<input type="checkbox"/> Finger Stick	<input type="checkbox"/> With Ride Control	<input type="checkbox"/> Without Ride Control

ENGINE	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Bad	<input type="checkbox"/> Oil Leaking	
MAIN PUMP	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Bad	<input type="checkbox"/> Oil Leaking	
SWING BEARING	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Bad	<input type="checkbox"/> Oil Leaking	N/A
TRAVEL MOTOR	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Bad	<input type="checkbox"/> Oil Leaking	N/A
TRANSMISSION	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Bad	<input type="checkbox"/> Oil Leaking	
TORQUE CONVERTOR	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Bad	—	
BRAKING SYSTEM	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Bad	—	
APPEARANCE	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Bad	—	
UNDER CARRIAGE / TIRE	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Bad	—	
BOOM / CYLINDER	<input type="checkbox"/> No Crack	<input type="checkbox"/> Welded	<input type="checkbox"/> Patched	<input type="checkbox"/> Oil Leaking	N/A
ARM / CYLINDER	<input checked="" type="checkbox"/> No Crack	<input type="checkbox"/> Welded	<input type="checkbox"/> Patched	<input type="checkbox"/> Oil Leaking	
BATTERY	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Need To Charge		<input type="checkbox"/> Need To Change	
COMMENT					

This inspection information is for reference only. It is not to guarantee the condition of the actual machine.
 この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。