		INSPE	CTION INF	ORMATION				
MAKER	CAT		BLADE			Have	☐ No	
SPECIES	TRUCK & TRAILER		TIRE SIZE		23.5	R25	☐ Tube ☑	Tubeless
MODEL, SERIAL NO. D250E-5TN-01008				Maker		CAT		
PLATE NO. D250E-5		5TN01008	ENGINE		Model		3306B	
STAMP 5TN010		01008			S/No.	13Z38621		
YEAR MANUFACTURE	1997	Yr.	EPA			Have	☐ No	
SERVICE METER	10721 Hrs.		FRONT		☐ Std	Offset	Super Long	М
SERVICE WETER	Confirmed	Unreliable	TRONT		☐ 2Sec	☐ 3Sec	Demotion	М
SHOE WIDTH / TYPE			CAB		Rops	✓ Cab	☐ Canopy	☐ None
PIPING		☐ No	CAB		✓ With Air	r cond	☐ Without Ai	r Cond
ATTACHMENT	ACHMENT		排ガス規制					
BUCKET			書類 ✓	有 二 無		譲	渡証	
CHECK VALVE(クレーン付き)	☐ Have	□ No	MULTI LEVER			Have	☐ No	
	ed Dump Truck							
NOTE 23Tアーティキ	・ュレートダンプトラッ	ク						
☐ Straight Dozer	☐ With Tilt		Without Tilt	☐ Angle	Dozer	☐ 6way	Dozer	
☐ Direct Drive ☐ F	ower Shift	☐ Differential	Steering Power S	hift	Direct Power	shift	☐ H.S.T.	
☐ With Multi Ripper	☐ 2 Cylinder	☐ 4 Cylin	nder	Shank				
☐ With Giant Ripper	2 Cylinder	☐ 4 Cylin						
☐ 2Lever ☐4Lever	☐ Wrist Contro	ol \square	Finger Stick	☐ With	Ride Control	☐ Witho	ut Ride Control	
ENGINE	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
MAIN PUMP	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
SWING BEARING	Good	☐ Fair	☐ Bad	☐ Oil Leaking	N/A			
TRAVEL MOTOR	Good	☐ Fair	☐ Bad	☐ Oil Leaking	N/A			
TRANSMISSION	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
TORQUE CONVERTOR	Good	✓ Fair	☐ Bad	_				
BRAKING SYSTEM	Good	✓ Fair	☐ Bad	_				
APPEARANCE	Good	✓ Fair	☐ Bad	_				
UNDER CARRIAGE / TIRI	Good	✓ Fair	☐ Bad	_				
BOOM / CYLINDER	☐ No Crack	Welded	☐ Patched	☐ Oil Leaking	N/A			
ARM / CYLINDER	☐ No Crack	Welded	☐ Patched	☐ Oil Leaking	N/A			
BATTERY	 Good	☐ Need To Ch	narge	Need To Change				
COMMENT								

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。