INSPECTION INFORMATION								
MAKER	KUBOTA		BLADE		✓	Have	🗌 No	
SPECIES	MINI EXCAVATOR		TIRE SIZE				🗌 Tube 🔲	Tubeless
MODEL, SERIAL NO.	U30-5-70884		ENGINE		Maker		KUBOTA	
PLATE NO. JKUU0305		000H70884			Model		D1703	
STAMP 708		884			S/No.		08A1032	
YEAR MANUFACTURE	2008	Yr.	EPA			Have	✓ No	
SERVICE METER	432	Hrs.	FRONT		✓ Std	Offset	□ Super Long	М
SERVICE METER	Confirmed	Unreliable			2Sec	3Sec	Demotion	М
SHOE WIDTH / TYPE		BBER	САВ		🗌 Rops	🗌 Cab	Canopy	None
PIPING	✓ Have	No No	CAB		🔲 With Air	r cond	U Without Air	Cond
ATTACHMENT			排ガス規制		3次排ガス			
BUCKET	0.0	9 M3	書類	有 🗹 無				
CHECK VALVE(クレーン付き)	🗌 Have	✓ No	MULTI LEVER			Have	🗹 No	
NOTE								
Straight Dozer With Tilt Without Tilt Angle Dozer Gway Dozer								
Direct Drive Power Shift Differential Steering Power Shift Direct Powershift H.S.T.								
With Multi Ripper 2 Cylinder 4 Cylinder Shank								
With Giant Ripper 2 Cylinder 4 Cylinder								
2Lever 4Lever	Wrist Contro	bl 🗌	Finger Stick	U With	Ride Control	U Witho	ut Ride Control	
ENGINE	Good	✓ Fair	🗌 Bad	Oil Leaking				
MAIN PUMP	🗌 Good	✓ Fair	☐ Bad	Oil Leaking				
SWING BEARING	🗌 Good	✓ Fair	Bad	Oil Leaking				
TRAVEL MOTOR	Good Good	✓ Fair	Bad	Oil Leaking				
TRANSMISSION	Good	E Fair	Bad	Oil Leaking	N/A			
TORQUE CONVERTOR	🗌 Good	E Fair	Bad	_	N/A			
BRAKING SYSTEM	🗌 Good	E Fair	🗌 Bad	_	N/A			
APPEARANCE	Good	✓ Fair	🗌 Bad	_				
UNDER CARRIAGE / TIRE	🗌 Good	✓ Fair	🗌 Bad	_				
BOOM / CYLINDER	No Crack	Welded	Patched	Oil Leaking				
ARM / CYLINDER	No Crack	Welded	Patched	Oil Leaking				
BATTERY	✓ Good	Need To Cr	narge 🗌	Need To Change				
COMMENT								

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。