		INSPE	CTION INF	ORMATION			
MAKER	KOBELCO		BLADE		☐ Have		✓ No
SPECIES	EXCAVATOR		TIRE SIZE				☐ Tube ☐ Tubeless
MODEL, SERIAL NO. SK135SRLC-1		ES-YH04-03294			Maker		ISUZU
PLATE NO.	YH04	YH04-03294		ENGINE			BB-4BG1T
STAMP	YH04	YH04-03294				906876	
YEAR MANUFACTURE	2005	Yr.	EPA		✓	Have	□ No
SERVICE METER	5571	Hrs.	FRONT		☐ Std	☐ Offset	✓ Super Long 12 M
SERVICE METER	✓ Confirmed	Unreliable			☐ 2Sec	☐ 3Sec	☐ Demotion M
SHOE WIDTH / TYPE	500G W/PAD		CAB		Rops	✓ Cab	☐ Canopy ☐ None
PIPING	☐ Have	✓ No	CAB		✓ With Air	cond	☐ Without Air Cond
ATTACHMENT			排ガス規制		1次排ガス		
BUCKET	0.2	2 M3	書類	有 ☑ 無			
CHECK VALVE(クレーン付き	) Have	✓ No	MULTI LEVER		✓	Have	☐ No
	al Counter Weight						
NOTE 増カウンター	ウエイト有り						
☐ Straight Dozer ☐ With Tilt ☐ Without Tilt ☐ Angle Dozer ☐ 6way Dozer							Dozer
☐ Direct Drive ☐ Power Shift ☐ Differential Steering Power Shift ☐ Direct Powershift ☐ H.S.T.							
☐ With Multi Ripper	2 Cylinder	☐ 4 Cylin	nder	Shank			
☐ With Giant Ripper	2 Cylinder	☐ 4 Cylin	nder				
□ 2Lever □4Lever □ Wrist Control □ Finger Stick □ With Ride Control □ Without Ride Control							
ENGINE	Good	✓ Fair	☐ Bad	☐ Oil Leaking			
MAIN PUMP	Good	✓ Fair	☐ Bad	☐ Oil Leaking			
SWING BEARING	Good	✓ Fair	☐ Bad	☐ Oil Leaking			
TRAVEL MOTOR	Good	✓ Fair	☐ Bad	☐ Oil Leaking			
TRANSMISSION	Good	☐ Fair	☐ Bad	☐ Oil Leaking	N/A		
TORQUE CONVERTOR	Good	☐ Fair	☐ Bad	_	N/A		
BRAKING SYSTEM	Good	☐ Fair	☐ Bad	_	N/A		
APPEARANCE	Good	✓ Fair	☐ Bad	_			
UNDER CARRIAGE / TIF	E Good	✓ Fair	☐ Bad	_			
BOOM / CYLINDER	✓ No Crack	☐ Welded	☐ Patched	☐ Oil Leaking			
ARM / CYLINDER	✓ No Crack	☐ Welded	☐ Patched	☐ Oil Leaking			
BATTERY	✓ Good	☐ Need To Ch	narge 🗆	Need To Change			
COMMENT			,				

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。