		INSPE	CTION INFO	ORMATION				
MAKER	KOMATSU		BLADE		<b>✓</b>	Have	☐ No	
SPECIES	MINI EXC	CAVATOR	TIRE SIZE				☐ Tube ☐	Tubeless
MODEL, SERIAL NO.	PC30MR-3-34600				Maker	YANMAR		
PLATE NO. KMTPC200C04034600		ENGINE		Model	3D88E-6BPDA			
STAMP	KMTPC200C04034600				S/No.	16819		
YEAR MANUFACTURE	2011	Yr.	EPA		✓	Have	☐ No	
SERVICE METER	2135	Hrs.	FRONT		✓ Std	☐ Offset	Super Long	М
SERVICE METER	✓ Confirmed	Unreliable			☐ 2Sec	☐ 3Sec	Demotion	М
SHOE WIDTH / TYPE	GROUSE	ER W/PAD	САВ		✓ Rops	☐ Cab	✓ Canopy	☐ None
PIPING	☐ Have	✓ No			☐ With Air	cond	✓ Without A	ir Cond
ATTACHMENT			排ガス規制					
BUCKET			書類   ✓	有   無	譲渡証			
CHECK VALVE(クレーン付き)	☐ Have	✓ No	MULTI LEVER			Have	✓ No	
NOTE  Straight Dozer	☐ With Tilt		Without Tilt	☐ Angle	Dozer	□ 6way	Dozer	
— William — Will								
□ Direct Drive □ Power Shift □ Differential Steering Power Shift □ Direct Powershift □ H.S.T. □ With Multi Ripper □ 2 Cylinder □ 4 Cylinder □ Shank								
☐ With Giant Ripper	2 Cylinder	☐ 4 Cylin						
☐ 2Lever ☐4Lever								
ENGINE	☐ Good	✓ Fair	☐ Bad	☐ Oil Leaking				
MAIN PUMP	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
SWING BEARING	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
TRAVEL MOTOR	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
TRANSMISSION	Good	☐ Fair	☐ Bad	☐ Oil Leaking	N/A			
TORQUE CONVERTOR	Good	☐ Fair	☐ Bad	_	N/A			
BRAKING SYSTEM	Good	☐ Fair	☐ Bad	_	N/A			
APPEARANCE	Good	✓ Fair	☐ Bad	_				
UNDER CARRIAGE / TIRE	☐ Good	✓ Fair	☐ Bad	_				
BOOM / CYLINDER	✓ No Crack	Welded	☐ Patched	☐ Oil Leaking				
ARM / CYLINDER	✓ No Crack	Welded	☐ Patched	Oil Leaking				
BATTERY	<b>✓</b> Good	☐ Need To Ch	narge	Need To Change				
COMMENT								

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。