| | | INSPE | ECTION INF | ORMATION | | | | |
|-----------------------------------------------------------------------------------------------|------------------|--------------|--------------|----------------|--------------|----------|-----------------|----------|
| MAKER | CAT | | BLADE | | | Have | ☐ No | |
| SPECIES | EXCAVATOR | | TIRE SIZE | | | | ☐ Tube ☐ | Tubeless |
| MODEL, SERIAL NO. | 320D-E-BWZ-06775 | | ENGINE | | Maker | | CAT | |
| PLATE NO. CAT0320D | | LBWZ06775 | | | Model | | C6.4 | |
| STAMP | MP CAT0320DLBWZ0 | | | | S/No. | GDC65974 | | |
| YEAR MANUFACTURE | 2012 | Yr. | EPA | | | Have | ✓ No | |
| SERVICE METER | 5828 | Hrs. | FRONT | | ✓ Std | ☐ Offset | □ Super Long | М |
| SERVICE WETER | ✓ Confirmed | ☐ Unreliable | | | ☐ 2Sec | ☐ 3Sec | ☐ Demotion | М |
| SHOE WIDTH / TYPE 6 | | 00G | CAB | | Rops | ✓ Cab | ☐ Canopy | ☐ None |
| PIPING | ☐ Have | ✓ No | CAB | | ✓ With Air | cond | ☐ Without Air | Cond |
| ATTACHMENT | | | 排ガス規制 | | 3次排ガス | | | |
| BUCKET | 0.8M3 | | 書類 | 有 | | | | |
| CHECK VALVE(クレーン付き) | ✓ Have | □ No | MULTI LEVER | | ✓ | Have | ☐ No | |
| NOTE | | | | | | | | |
| ☐ Straight Dozer | ☐ With Tilt | | Without Tilt | ☐ Angle | Dozer | ☐ 6way I | Dozer | |
| □ Direct Drive □ Power Shift □ Differential Steering Power Shift □ Direct Powershift □ H.S.T. | | | | | | | | |
| ☐ With Multi Ripper | ☐ 2 Cylinder | ☐ 4 Cylir | nder | Shank | | | | |
| ☐ With Giant Ripper | 2 Cylinder | ☐ 4 Cylir | nder | | | | | |
| ☐ 2Lever ☐4Lever | ☐ Wrist Contro | ol 🗆 | Finger Stick | ☐ With | Ride Control | ☐ Withou | ut Ride Control | |
| ENGINE | Good | ✓ Fair | ☐ Bad | ☐ Oil Leaking | | | | |
| MAIN PUMP | Good | ✓ Fair | ☐ Bad | ☐ Oil Leaking | | | | |
| SWING BEARING | Good | ✓ Fair | ☐ Bad | ☐ Oil Leaking | | | | |
| TRAVEL MOTOR | Good | ✓ Fair | ☐ Bad | ☐ Oil Leaking | | | | |
| TRANSMISSION | Good | ☐ Fair | ☐ Bad | ☐ Oil Leaking | N/A | | | |
| TORQUE CONVERTOR | Good | ☐ Fair | ☐ Bad | _ | N/A | | | |
| BRAKING SYSTEM | Good | ☐ Fair | ☐ Bad | _ | N/A | | | |
| APPEARANCE | Good | ✓ Fair | ☐ Bad | _ | | | | |
| UNDER CARRIAGE / TIRE | Good | ✓ Fair | ☐ Bad | _ | | | | |
| BOOM / CYLINDER | ✓ No Crack | ☐ Welded | ☐ Patched | ☐ Oil Leaking | | | | |
| ARM / CYLINDER | ✓ No Crack | ☐ Welded | ☐ Patched | ☐ Oil Leaking | | | | |
| BATTERY | ✓ Good | ☐ Need To Ch | narge | Need To Change | | | | |
| COMMENT | | | | | | | | |

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。