		INSPE	CTION INF	ORMATION				
MAKER	CAT		BLADE			Have	☐ No	
SPECIES TRUCK & T		& TRAILER	TIRE SIZE				☐ Tube ☐	Tubeless
MODEL, SERIAL NO.	740-B ²	1P-03604			Maker		CAT	
PLATE NO.		ENGINE		ENGINE			C15-JE3-TAA	
STAMP					S/No.			
YEAR MANUFACTURE	2008	Yr.	EPA		✓	Have	☐ No	
SERVICE METER	11051			FRONT		Offset	Super Long	М
SERVICE METER	✓ Confirmed	Unreliable	FRONT		☐ 2Sec	☐ 3Sec	☐ Demotion	М
SHOE WIDTH / TYPE			САВ		Rops	☐ Cab	☐ Canopy	☐ None
PIPING	☐ Have	☐ No	-CAB		☐ With Air	cond	☐ Without Air	Cond
ATTACHMENT			排ガス規制					
BUCKET			書類	有 無				
CHECK VALVE(クレーン付	∌) ☐ Have	□ No	MULTI LEVER			Have	☐ No	
	CULATED DUMP TR	UCK						
NOTE 38Tアーティ	キュレートダンプトラッ	ク						
☐ Straight Dozer	☐ With Tilt		Without Tilt	☐ Angle	Dozer	☐ 6way	Dozer	
☐ Direct Drive ☐	Power Shift	☐ Differential	Steering Power S	hift	Direct Power	shift	☐ H.S.T.	
☐ With Multi Ripper	☐ 2 Cylinder	☐ 4 Cylir	nder	Shank				
☐ With Giant Ripper	2 Cylinder	☐ 4 Cylir	nder					
☐ 2Lever ☐4Lev	er Wrist Contr	ol	Finger Stick	☐ With I	Ride Control	☐ Witho	ut Ride Control	
ENGINE	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
MAIN PUMP	Good	✓ Fair	☐ Bad	Oil Leaking				
SWING BEARING	Good	☐ Fair	☐ Bad	Oil Leaking	N/A			
TRAVEL MOTOR	Good	☐ Fair	☐ Bad	Oil Leaking	N/A			
TRANSMISSION	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
TORQUE CONVERTO	R Good	✓ Fair	☐ Bad	_				
BRAKING SYSTEM	Good	✓ Fair	☐ Bad					
APPEARANCE	Good	✓ Fair	☐ Bad					
UNDER CARRIAGE / T	RE Good	✓ Fair	☐ Bad					
BOOM / CYLINDER	☐ No Crack	☐ Welded	☐ Patched	☐ Oil Leaking	N/A			
ARM / CYLINDER	☐ No Crack	☐ Welded	☐ Patched	☐ Oil Leaking	N/A			
BATTERY	✓ Good	☐ Need To Ch	narge 🗆	Need To Change				
COMMENT			•					

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。