		INSPE	CTION INFO	ORMATION				
MAKER	CAT		BLADE		☐ Have		✓ No	
SPECIES	EXCA	VATOR	TIRE SIZE				☐ Tube ☐ Tub	oeless
MODEL, SERIAL NO.	311DRR-AKW-00115		ENGINE		Maker		CAT	
PLATE NO. CAT0311D		TAKW00115			Model		KDPC4.2	
STAMP	CAT0311DTAKW00115				S/No.			
YEAR MANUFACTURE	2007	Yr.	EPA			Have	✓ No	
SERVICE METER	3205	Hrs.	FRONT		✓ Std	☐ Offset	Super Long	М
SERVICE WETER	✓ Confirmed	Unreliable	TROW		☐ 2Sec	☐ 3Sec	☐ Demotion I	М
SHOE WIDTH / TYPE 500G V		W/PAD	CAB		Rops	✓ Cab	☐ Canopy ☐	None
PIPING	☐ Have	☐ No	CAB		✓ With Air	cond	☐ Without Air Cor	nd
ATTACHMENT			排ガス規制		3次排ガス			
BUCKET			書類	有				
CHECK VALVE(クレーン付き)	✓ Have	□ No	MULTI LEVER		✓	Have	☐ No	
NOTE								
☐ Straight Dozer	☐ With Tilt		Without Tilt	☐ Angle	Dozer	☐ 6way [Dozer	
☐ Direct Drive ☐ Power Shift ☐ Differential Steering Power Shift ☐ Direct Powershift ☐ H.S.T.						☐ H.S.T.		
☐ With Multi Ripper	☐ 2 Cylinder	☐ 4 Cylin	der	Shank				
☐ With Giant Ripper	2 Cylinder	☐ 4 Cylin	der					
☐ 2Lever ☐4Lever	☐ Wrist Contro	ol 🗆	Finger Stick	☐ With I	Ride Control	☐ Withou	ut Ride Control	
ENGINE	Good	✓ Fair	Bad	Oil Leaking				
MAIN PUMP	Good	✓ Fair	Bad	Oil Leaking				
SWING BEARING	Good	✓ Fair	Bad	Oil Leaking				
TRAVEL MOTOR	Good	✓ Fair	Bad	Oil Leaking				
TRANSMISSION	Good	☐ Fair	Bad	Oil Leaking	N/A			
TORQUE CONVERTOR	Good	☐ Fair	Bad	_	N/A			
BRAKING SYSTEM	Good	☐ Fair	☐ Bad	_	N/A			
APPEARANCE	Good	✓ Fair	Bad	_				
UNDER CARRIAGE / TIRE	Good	✓ Fair	☐ Bad	_				
BOOM / CYLINDER	✓ No Crack	Welded	☐ Patched	Oil Leaking				
ARM / CYLINDER	✓ No Crack		☐ Patched	☐ Oil Leaking				
BATTERY	✓ Good	☐ Need To Ch	arge 🗆	Need To Change				
COMMENT								

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。