		INSPE	CTION INFO	ORMATION				
MAKER	HITACHI		BLADE		✓	Have	☐ No	
SPECIES	MINI EXC	NI EXCAVATOR TIRE SIZE					☐ Tube ☐	Tubeless
MODEL, SERIAL NO.	ZX20UR-10059		ENGINE		Maker	IHI		
PLATE NO. HCM1MU00P00010059		0P00010059			Model		S773L-C	
STAMP					S/No.	2702		
YEAR MANUFACTURE	2007	Yr.	EPA		✓	Have	☐ No	
CEDVICE METER	3602	Hrs.	FRONT		☐ Std	✓ Offset	□ Super Long	М
SERVICE METER	✓ Confirmed	Unreliable			☐ 2Sec	☐ 3Sec	☐ Demotion	М
SHOE WIDTH / TYPE	1 / TYPE RUBBER		CAR		Rops	☐ Cab	✓ Canopy	☐ None
PIPING	☐ Have	✓ No	CAB		☐ With Air	cond	✓ Without A	ir Cond
ATTACHMENT			排ガス規制		3次排ガス			
BUCKET			書類	有				
CHECK VALVE(クレーン付き)	☐ Have	✓ No	MULTI LEVER		✓	Have	☐ No	
NOTE					_			
☐ Straight Dozer ☐ With Tilt ☐ Without Tilt ☐ Angle Dozer ☐ 6way Dozer								
□ Direct Drive □ Power Shift □ Differential Steering Power Shift □ Direct Powershift □ H.S.T.								
☐ With Multi Ripper	☐ 2 Cylinder	☐ 4 Cylin		Shank				
☐ With Giant Ripper ☐ 2 Cylinder ☐ 4 Cylinder								
☐ 2Lever ☐4Lever	☐ Wrist Contro	ol 🗆	Finger Stick	☐ With I	Ride Control	vvitnoi	ut Ride Control	
ENGINE	☐ Good	<b>√</b> Fair	☐ Bad	Oil Leaking				
MAIN PUMP	☐ Good	✓ Fair	☐ Bad	Oil Leaking				
SWING BEARING	Good	✓ Fair	☐ Bad	Oil Leaking				
TRAVEL MOTOR	Good	✓ Fair	☐ Bad	Oil Leaking				
TRANSMISSION	☐ Good	☐ Fair	☐ Bad	Oil Leaking	N/A			
TORQUE CONVERTOR	Good	☐ Fair	☐ Bad	_	N/A			
BRAKING SYSTEM	☐ Good	☐ Fair	☐ Bad	_	N/A			
APPEARANCE	Good	✓ Fair	☐ Bad	_				
UNDER CARRIAGE / TIRE	☐ Good	✓ Fair	☐ Bad	_				
BOOM / CYLINDER	✓ No Crack	Welded	☐ Patched	Oil Leaking				
ARM / CYLINDER	✓ No Crack	Welded	☐ Patched	Oil Leaking				
BATTERY	<b></b> Good	☐ Need To Ch	arge 🗆	Need To Change				
COMMENT								

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。