		INSPE	CTION INF	ORMATION				
MAKER	YANMAR		BLADE		✓	Have	☐ No	
SPECIES	MINI EXCAVATOR		TIRE SIZE				☐ Tube ☐	Tubeless
MODEL, SERIAL NO.	DEL, SERIAL NO. B22-2-12793B		ENGINE		Maker		YANMAR	
PLATE NO.					Model	3TNE78A-B1		
STAMP 12793B]		S/No.				
YEAR MANUFACTURE	2001	Yr.	EPA			Have	✓ No	
OFD. ((OF METER	3805	Hrs.	ED ON E		✓ Std	☐ Offset	□ Super Long	M
SERVICE METER	Confirmed	Unreliable	FRONT		☐ 2Sec	☐ 3Sec	☐ Demotion	М
SHOE WIDTH / TYPE RUBBI		BBER	САВ		Rops	☐ Cab	✓ Canopy	☐ None
PIPING	☐ Have	✓ No	CAB		☐ With Air	r cond	✓ Without A	ir Cond
ATTACHMENT			排ガス規制		1次排ガス			
BUCKET			書類	有 無				
CHECK VALVE(クレーン付き)	☐ Have	✓ No	MULTI LEVER			Have	✓ No	
NOTE Straight Dozer	☐ With Tilt		Without Tilt	☐ Angle	Dozer	☐ 6way I	Dozer	
☐ Straight Dozer ☐ With Tilt ☐ Without Tilt ☐ Angle Dozer ☐ 6way Dozer ☐ Direct Drive ☐ Power Shift ☐ Differential Steering Power Shift ☐ Direct Powershift ☐ H.S.T.								
☐ With Multi Ripper	2 Cylinder	☐ 4 Cylin		Shank	Direct Tower	OTHIT .		
☐ With Giant Ripper	2 Cylinder	☐ 4 Cylin	nder					
☐ 2Lever ☐4Lever	☐ Wrist Contro	ol 🗆	Finger Stick	☐ With I	Ride Control	☐ Withou	ut Ride Control	
ENGINE	Good	✓ Fair	Bad	☐ Oil Leaking				
MAIN PUMP	☐ Good	✓ Fair	☐ Bad	Oil Leaking				
SWING BEARING	☐ Good	✓ Fair	☐ Bad	☐ Oil Leaking				
TRAVEL MOTOR	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
TRANSMISSION	Good	☐ Fair	Bad	☐ Oil Leaking	N/A			
TORQUE CONVERTOR	Good	☐ Fair	☐ Bad	_	N/A			
BRAKING SYSTEM	Good	☐ Fair	☐ Bad	_	N/A			
APPEARANCE	Good	✓ Fair	☐ Bad	_				
UNDER CARRIAGE / TIRE	☐ Good	✓ Fair	☐ Bad	_				
BOOM / CYLINDER	✓ No Crack	Welded	Patched	☐ Oil Leaking				
ARM / CYLINDER	✓ No Crack	☐ Welded	☐ Patched	☐ Oil Leaking				
BATTERY	✓ Good	☐ Need To Ch	narge 🗆	Need To Change				
COMMENT								

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。