

INSPECTION INFORMATION

MAKER	CAT	BLADE	<input type="checkbox"/> Have	<input checked="" type="checkbox"/> No		
SPECIES	EXCAVATOR	TIRE SIZE	<input type="checkbox"/> Tube <input type="checkbox"/> Tubeless			
MODEL, SERIAL NO.	330DL-RDK-00135	ENGINE	Maker	CAT (Rebuilt 2015YR)		
PLATE NO.			Model	C9		
STAMP			S/No.	DYA00749		
YEAR MANUFACTURE	2007 Yr.	EPA	<input type="checkbox"/> Have	<input type="checkbox"/> No		
SERVICE METER	9396 Hrs.	FRONT	<input type="checkbox"/> Std	<input type="checkbox"/> Offset	<input type="checkbox"/> Super Long	M
	<input checked="" type="checkbox"/> Confirmed <input type="checkbox"/> Unreliable		<input type="checkbox"/> 2Sec	<input type="checkbox"/> 3Sec	<input type="checkbox"/> Demotion	M
SHOE WIDTH / TYPE	700G	CAB	<input type="checkbox"/> Rops	<input type="checkbox"/> Cab	<input type="checkbox"/> Canopy	<input type="checkbox"/> None
PIPING	<input type="checkbox"/> Have <input type="checkbox"/> No		<input type="checkbox"/> With Air cond	<input type="checkbox"/> Without Air Cond		
ATTACHMENT		排ガス規制	3次排ガス (Tier 3)			
BUCKET		書類 <input type="checkbox"/> 有 <input type="checkbox"/> 無				
CHECK VALVE (クレーン付き)	<input type="checkbox"/> Have <input type="checkbox"/> No	MULTI LEVER	<input checked="" type="checkbox"/> Have	<input type="checkbox"/> No		
NOTE	2pcs Boom & 21M 3Sec. Demolition Front 2ピースブーム&3段解体用フロント					

<input type="checkbox"/> Straight Dozer	<input type="checkbox"/> With Tilt	<input type="checkbox"/> Without Tilt	<input type="checkbox"/> Angle Dozer	<input type="checkbox"/> 6way Dozer
<input type="checkbox"/> Direct Drive	<input type="checkbox"/> Power Shift	<input type="checkbox"/> Differential Steering Power Shift	<input type="checkbox"/> Direct Powershift	<input type="checkbox"/> H.S.T.
<input type="checkbox"/> With Multi Ripper	<input type="checkbox"/> 2 Cylinder	<input type="checkbox"/> 4 Cylinder	<input type="checkbox"/> Shank	
<input type="checkbox"/> With Giant Ripper	<input type="checkbox"/> 2 Cylinder	<input type="checkbox"/> 4 Cylinder		
<input type="checkbox"/> 2Lever	<input type="checkbox"/> 4Lever	<input type="checkbox"/> Wrist Control	<input type="checkbox"/> Finger Stick	<input type="checkbox"/> With Ride Control <input type="checkbox"/> Without Ride Control

ENGINE	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Bad	<input type="checkbox"/> Oil Leaking	
MAIN PUMP	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Bad	<input type="checkbox"/> Oil Leaking	
SWING BEARING	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Bad	<input type="checkbox"/> Oil Leaking	
TRAVEL MOTOR	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Bad	<input type="checkbox"/> Oil Leaking	N/A
TRANSMISSION	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Bad	<input type="checkbox"/> Oil Leaking	N/A
TORQUE CONVERTOR	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Bad	—	N/A
BRAKING SYSTEM	<input type="checkbox"/> Good	<input type="checkbox"/> Fair	<input type="checkbox"/> Bad	—	N/A
APPEARANCE	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Bad	—	
UNDER CARRIAGE / TIRE	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Fair	<input type="checkbox"/> Bad	—	
BOOM / CYLINDER	<input checked="" type="checkbox"/> No Crack	<input type="checkbox"/> Welded	<input type="checkbox"/> Patched	<input type="checkbox"/> Oil Leaking	
ARM / CYLINDER	<input checked="" type="checkbox"/> No Crack	<input type="checkbox"/> Welded	<input type="checkbox"/> Patched	<input type="checkbox"/> Oil Leaking	
BATTERY	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Need To Charge		<input type="checkbox"/> Need To Change	
COMMENT	Engine Replaced CAT Reman One and Hyd. Pump Replaced New One When 8634H 8634時間のとき、リマン エンジンに乗せ換え、ポンプ新品交換				

This inspection information is for reference only. It is not to guarantee the condition of the actual machine.
この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。