INSPECTION INFORMATION													
MAKER		KOMATSU			BLADE				☐ Have		✓ No		
SPECIES		EXCAVATOR			TIRE SIZE					☐ Tube	Tubeless		
MODEL, SERIAL NO.		PC450LC-7EO-65197						Maker		KOMATSU			
PLATE NO.		KMTPC184A02065197			ENGINE				Model	SAA6D125E-5			
STAMP		KMTPC184A02065197							S/No.		563591		
YEAR MANUFACTURE		2007			Yr.	EPA				✓	Have	□ N	-
SERVICE METER		5466 Hrs			Hrs.	-FRONT				☐ Std	Offset	Super Long	
		✓ Confirmed □ Unreliable							☐ 2Sec	✓ 3Sec	✓ Demotion	on 27 M	
SHOE WIDTH / TYPE		600G			CAB			Rops	✓ Cab	☐ Canopy	☐ None		
PIPING		Have(5pipes) No		✓ With Air				r cond	☐ Without	Air Cond			
ATTACHMENT					排ガス規制				2次排ガス				
BUCKET						書類		有	☑ 無				
CHECK VALVE (クレーン付き)			Have	✓	No	MULT	I LEVER				Have	✓ N	0
2pc. Boom Front & 27M 3sec. Demolition Front NOTE 2ピースブームフロント&27M 3段解体用フロント													
☐ Straight Dozer ☐ With Tilt ☐ Without Tilt ☐ Angle Dozer ☐ 6way Dozer													
☐ Direct Dri	ve 🗌 Po	ower S	wer Shift Differential S				Steering Power Shift						
☐ With Multi Ripper		☐ 2 Cylinder ☐ 4 Cylin				nder	der 🗌 Shank						
☐ With Gi	ant Ripper	2 Cylinder 4 Cylin				nder							
☐ 2Lever ☐4Lever		☐ Wrist Control ☐			Finger Stick			Ride Control	☐ Withou	ut Ride Contro	ol		
ENG	GINE		Good	√	Fair		Bad		Oil Leaking				
MAIN PUMP			Good	✓	Fair		Bad		Oil Leaking				
SWING BEARING			Good	✓	Fair		Bad		Oil Leaking				
TRAVEL MOTOR			Good	✓	Fair		Bad		Oil Leaking				
TRANSMISSION			Good		Fair		Bad		Oil Leaking	N/A			
TORQUE CONVERTOR			Good		Fair		Bad		_	N/A			
BRAKING SYSTEM			Good		Fair		Bad		_	N/A			
APPEARANCE			Good	✓	Fair		Bad		_				
UNDER CARRIAGE / TIRE			Good	✓	Fair		Bad		_				
BOOM / CYLINDER		✓	No Crack		Welded		Patched		Oil Leaking				
ARM / CYLINDER			No Crack		Welded	✓	Patched		Oil Leaking	2 Piece From 2ピースフロン			
BATTERY		✓	Good		Need To Ch	narge	rge Need To Change						
COMMENT													

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。