		INSPE	CTION INFO	ORMATION				
MAKER	KOMATSU		BLADE		✓	Have	☐ No	
SPECIES	MINI EX	CAVATOR	VATOR TIRE SIZE				☐ Tube ☐	Tubeless
MODEL, SERIAL NO.	PC20MR-3-20569				Maker	KOMATSU		
PLATE NO. KMTPC215T04020569		ENGINE		Model	3D76E-6NDA			
STAMP	KMTPC215T04020569				S/No.	06022		
YEAR MANUFACTURE	2010	Yr.	EPA			Have	✓ No	
SERVICE METER	2049	Hrs.	FRONT		✓ Std	☐ Offset	Super Long	М
SERVICE METER	✓ Confirmed	Unreliable			☐ 2Sec	☐ 3Sec	Demotion	М
SHOE WIDTH / TYPE	RUBBER		CAB		✓ Rops	☐ Cab	✓ Canopy	☐ None
PIPING	☐ Have	✓ No	CAB		☐ With Air	cond	☐ Without Ai	r Cond
ATTACHMENT			排ガス規制		3次排ガス			
BUCKET	0.0	7 M3	書類	有				
CHECK VALVE(クレーン付き)	☐ Have	✓ No	MULTI LEVER		✓	Have	☐ No	
NOTE								
☐ Straight Dozer ☐ With Tilt ☐ Without Tilt ☐ Angle Dozer ☐ 6way Dozer								
☐ Direct Drive ☐ Power Shift ☐ Differential Steering Power Shift ☐ Direct Powershift ☐ H.S.T.								
☐ With Multi Ripper	2 Cylinder	☐ 4 Cylin		Shank				
☐ With Giant Ripper ☐ 2 Cylinder ☐ 4 Cylinder								
□ 2Lever □4Lever □ Wrist Control □ Finger Stick □ With Ride Control □ Without Ride Control								
ENGINE	Good	✓ Fair	Bad	Oil Leaking				
MAIN PUMP	Good	✓ Fair	Bad	Oil Leaking				
SWING BEARING	Good	✓ Fair	☐ Bad	Oil Leaking				
TRAVEL MOTOR	Good	✓ Fair	Bad	Oil Leaking				
TRANSMISSION	Good	☐ Fair	Bad	Oil Leaking	N/A			
TORQUE CONVERTOR	Good	☐ Fair	Bad	_	N/A			
BRAKING SYSTEM	Good	☐ Fair	☐ Bad	_	N/A			
APPEARANCE	Good	✓ Fair	Bad	_				
UNDER CARRIAGE / TIRE	☐ Good	✓ Fair	☐ Bad	_				
BOOM / CYLINDER	✓ No Crack	Welded	☐ Patched	Oil Leaking				
ARM / CYLINDER	✓ No Crack	Welded	☐ Patched	☐ Oil Leaking				
BATTERY	✓ Good	☐ Need To Ch	narge 🗆	Need To Change				
COMMENT								

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。