		INSPE	CTION INFO	ORMATION				
MAKER	KOMATSU		BLADE		✓	Have	☐ No	
SPECIES	MINI EX	CAVATOR	VATOR TIRE SIZE				☐ Tube ☐	Tubeless
MODEL, SERIAL NO.	PC30MR-3-34301				Maker		YANMAR	
PLATE NO. KMTPC200C040		OC04034301	ENGINE		Model	3D88E-6BPDA		
STAMP	KMTPC200C04034301				S/No.	16155		
YEAR MANUFACTURE	2011	Yr.	EPA		✓	Have	☐ No	
SERVICE METER	2404 Hrs.		FRONT		✓ Std	☐ Offset	Super Long	М
SERVICE METER	✓ Confirmed	Unreliable	PROM		☐ 2Sec	☐ 3Sec	☐ Demotion	М
SHOE WIDTH / TYPE RUBBER		BBER	CAB		✓ Rops	☐ Cab	✓ Canopy	☐ None
PIPING	☐ Have	✓ No	CAB		☐ With Air	cond	☐ Without Ai	r Cond
ATTACHMENT			排ガス規制		3次排ガス			
BUCKET	0.0	9 M3	書類	有 無				
CHECK VALVE(クレーン付き)	✓ Have	□ No	MULTI LEVER		✓	Have	☐ No	
NOTE								
☐ Straight Dozer	☐ With Tilt		Without Tilt	☐ Angle	Dozer	☐ 6way	Dozer	
☐ Direct Drive ☐ Power Shift ☐ Differential Steering Power Shift ☐ Direct Powershift ☐ H.S.T.								
☐ With Multi Ripper	☐ 2 Cylinder	☐ 4 Cylin	der	Shank				
☐ With Giant Ripper ☐ 2 Cylinder ☐ 4 Cylinder								
□ 2Lever □4Lever □ Wrist Control □ Finger Stick □ With Ride Control □ Without Ride Control								
ENGINE	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
MAIN PUMP	Good	✓ Fair	Bad	Oil Leaking				
SWING BEARING	Good	✓ Fair	☐ Bad	Oil Leaking				
TRAVEL MOTOR	Good	✓ Fair	Bad	Oil Leaking				
TRANSMISSION	Good	☐ Fair	Bad	Oil Leaking	N/A			
TORQUE CONVERTOR	Good	☐ Fair	Bad	_	N/A			
BRAKING SYSTEM	Good	☐ Fair	Bad	_	N/A			
APPEARANCE	Good	✓ Fair	Bad	_				
UNDER CARRIAGE / TIRE	Good	✓ Fair	☐ Bad	_				
BOOM / CYLINDER	✓ No Crack	Welded	Patched	Oil Leaking				
ARM / CYLINDER	✓ No Crack	Welded	Patched	Oil Leaking				
BATTERY	 Good	☐ Need To Ch	arge 🗆	Need To Change				
COMMENT								

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。