INSPECTION INFORMATION								
MAKER	YANMAR		BLADE			Have	☐ No	
SPECIES	CARRIER DUMP		TIRE SIZE				☐ Tube ☐	Tubeless
MODEL, SERIAL NO. C12R-A-23096C				Maker		YANMAR		
PLATE NO. 230		)96C	ENGINE		Model		2TE67L-FW	
STAMP					S/No.		03234	
YEAR MANUFACTURE	2006	Yr.	EPA		✓	Have	□ No	
SERVICE METER	1450	Hrs.	FRONT		☐ Std	☐ Offset	Super Long	М
SERVICE WETER	✓ Confirmed	Unreliable			☐ 2Sec	☐ 3Sec	☐ Demotion	М
SHOE WIDTH / TYPE RUBB		BER	CAB		Rops	☐ Cab	☐ Canopy	☐ None
PIPING	☐ Have	☐ No	CAB		☐ With Air	cond	☐ Without Air	Cond
ATTACHMENT			排ガス規制					
BUCKET			書類	有 ☑ 無				
CHECK VALVE(クレーン付き)	☐ Have	□ No	MULTI LEVER			Have	☐ No	
NOTE EPA								
☐ Straight Dozer ☐ With Tilt ☐ Without Tilt ☐ Angle Dozer ☐ 6way Dozer								
☐ Direct Drive ☐ Power Shift ☐ Differential Steering Power Shift ☐ Direct Powershift ☐ H.S.T.								
☐ With Multi Ripper	With Multi Ripper ☐ 2 Cylinder ☐ 4 Cylinder ☐ Shank							
☐ With Giant Ripper ☐ 2 Cylinder ☐ 4 Cylinder								
☐ 2Lever ☐4Lever	☐ Wrist Contro	ol 🗆	Finger Stick	☐ With F	Ride Control	☐ Withou	ut Ride Control	
ENGINE	Good	✓ Fair	☐ Bad	Oil Leaking				
MAIN PUMP	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
SWING BEARING	Good	☐ Fair	☐ Bad	Oil Leaking	N/A			
TRAVEL MOTOR	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
TRANSMISSION	Good	☐ Fair	☐ Bad	☐ Oil Leaking	N/A			
TORQUE CONVERTOR	Good	☐ Fair	☐ Bad	_	N/A			
BRAKING SYSTEM	Good	Fair	☐ Bad	_	N/A			
APPEARANCE	Good	✓ Fair	☐ Bad	_				
UNDER CARRIAGE / TIRE	Good	✓ Fair	☐ Bad	_				
BOOM / CYLINDER	☐ No Crack	Welded	☐ Patched	☐ Oil Leaking	N/A			
ARM / CYLINDER	☐ No Crack	Welded	☐ Patched	☐ Oil Leaking	N/A			
BATTERY	✓ Good	☐ Need To Ch	narge 🗆	Need To Change				
COMMENT			-					

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。