		INSPE	CTION INF	ORMATION				
MAKER	KOMATSU		BLADE			Have	☐ No	
SPECIES	TRUCK & TRAILER		TIRE SIZE				☐ Tube ☑	Tubeless
MODEL, SERIAL NO. HM300-5-10331				Maker		KOMATSU		
PLATE NO.			ENGINE		Model	SAA6D125E-7		
STAMP					S/No.	861428		
YEAR MANUFACTURE	2017	Yr.	EPA			Have	✓ No	
SERVICE METER	2008 Hrs.		FRONT		☐ Std	☐ Offset	Super Long	М
SERVICE WETER	✓ Confirmed	Unreliable	FRONT		☐ 2Sec	☐ 3Sec	Demotion	М
SHOE WIDTH / TYPE			CAB		✓ Rops	✓ Cab	☐ Canopy	☐ None
PIPING	☐ Have	□ No	CAB		✓ With Air	cond	☐ Without Air	r Cond
ATTACHMENT			排ガス規制					
BUCKET			書類	有 ☑ 無				
CHECK VALVE(クレーン付き)	☐ Have	□ No	MULTI LEVER			Have	☐ No	
	ed Dump Truck, Ma	ade in Japan, Used i	in England					
NOTE 28Tアーティキ	・ュレートダンプ、日オ	×製、イギリスで使用						
☐ Straight Dozer	☐ With Tilt		Without Tilt	☐ Angle	Dozer	☐ 6way l	Dozer	
☐ Direct Drive ☐ F	Power Shift	☐ Differential	Steering Power S	Shift	Direct Power	shift	☐ H.S.T.	
☐ With Multi Ripper	☐ 2 Cylinder	☐ 4 Cylin	ider 🗌	Shank				
☐ With Giant Ripper	2 Cylinder	☐ 4 Cylin						
☐ 2Lever ☐4Lever	☐ Wrist Contro	ol $\square$	Finger Stick	☐ With	Ride Control	☐ Witho	ut Ride Control	
ENGINE	Good	✓ Fair	Bad	☐ Oil Leaking				
MAIN PUMP	Good	✓ Fair	Bad	☐ Oil Leaking				
SWING BEARING	Good	☐ Fair	☐ Bad	☐ Oil Leaking	N/A			
TRAVEL MOTOR	Good	☐ Fair	☐ Bad	☐ Oil Leaking	N/A			
TRANSMISSION	Good	✓ Fair	☐ Bad	☐ Oil Leaking				
TORQUE CONVERTOR	Good	✓ Fair	☐ Bad	_				
BRAKING SYSTEM	Good	✓ Fair	☐ Bad	_				
APPEARANCE	Good	✓ Fair	☐ Bad	_				
UNDER CARRIAGE / TIRI	Good	✓ Fair	☐ Bad	_				
BOOM / CYLINDER	☐ No Crack	Welded	Patched	☐ Oil Leaking	N/A			
ARM / CYLINDER	☐ No Crack	Welded	☐ Patched	☐ Oil Leaking	N/A			
BATTERY	✓ Good	☐ Need To Ch	narge	Need To Change				
COMMENT			-					

This inspection information is for reference only. It is not to guarantee the condition of the actual machine. この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。